

# PROJECT STATUS

## GRAFFITI BY SREEDHANYA

*Sree* **DHANYA**  
HOMES PVT. LTD



31.12.2025

## GRAFFITI WORK STATUS REPORT - 1 / 5

SL NO	ITEM OF WORK	OCTOBER	DECEMBER
A	STRUCTURAL & CIVIL WORK		
1	COLUMN WORK ABOVE TERRACE FLOOR	100% COMPLETED	100% COMPLETED
2	RCC FOR SWIMMING POOL	100% COMPLETED	100% COMPLETED
3	RCC FOR OHT	100% COMPLETED	100% COMPLETED
4	RCC FOR TERRACE FLOOR SLAB	100% COMPLETED	100% COMPLETED
5	UG SUMP WORK	100% COMPLETED	100% COMPLETED
B	MASONRY & PLASTERING		
1	BLOCK WORK	27/27 APTS COMPLETED	27/27 APTS COMPLETED
2	CEILING PLASTERING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
3	INSIDE WALL PLASTERING	100% COMPLETED	100% COMPLETED

## GRAFFITI WORK STATUS REPORT - 2/5

SL NO	ITEM OF WORK	OCTOBER	DECEMBER
C	ELECTRICAL WORK		
1	ELECTRICAL WALL CHASING & CONDUIT FIXING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
2	ELECTRICAL HT	95% COMPLETED	95% COMPLETED
3	APARTMENT INSIDE WIRING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
D	PLUMBING & WATERPROOFING		
1	APT INTERNAL PLUMBING WORK	27/27 APTS COMPLETED	27/27 APTS COMPLETED
2	DUCT PLUMBING WORK	100% COMPLETED	100% COMPLETED
3	INSIDE APT WATERPROOFING	27/27 APTS COMPLETED	27/27 APTS COMPLETED

## GRAFFITI WORK STATUS REPORT - 3/5

SL NO	ITEM OF WORK	OCTOBER	DECEMBER
E	TILING & FLOORING		
1	TOILET TILING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
2	APT FLOORING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
3	SWIMMING POOL TILING WORK	100% COMPLETED	100% COMPLETED, FILTERATION WORK ONGOING
F	PUTTY WORK		
1	WALL PUTTY WORK	27/27 APTS COMPLETED	27/27 APTS COMPLETED
2	INTERNAL PRIMER WORK	27/27 APTS COMPLETED	27/27 APTS COMPLETED
3	FIRST & SECOND COAT PAINTING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
4	EXTERNAL PRIMER & PAINTING	1ST COAT- 100%, 2 <sup>ND</sup> COAT- 50% COMPLETED	PRIMER-100%, 2 <sup>ND</sup> COAT PAINTING-100% COMPLETED



## GRAFFITI WORK STATUS REPORT - 4/5

SL NO	ITEM OF WORK	OCTOBER	DECEMBER
G	FIXTURES & FITTINGS		
1	BALCONY HANDRAIL FIXING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
2	UPVC DOORS & WINDOWS	27/27 APTS COMPLETED	27/27 APTS COMPLETED
3	GRILL FIXING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
4	PREHUNG DOORS FIXING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
5	CP SANITARY FIXING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
6	SWITCH FIXING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
H	COMMON AREA WORK		
1	LIFT INSTALLATION	100% COMPLETED	100% COMPLETED
2	STP	100% COMPLETED	100% COMPLETED


## GRAFFITI WORK STATUS REPORT - 5/5

SL NO	ITEM OF WORK	OCTOBER	DECEMBER
3	FIRE FIGHTING	98% COMPLETED	100% COMPLETED
4	GAS LINE WORKS	98% COMPLETED	98% COMPLETED
5	FALSE CEILING	27/27 APTS COMPLETED	27/27 APTS COMPLETED
6	TERRACE WORKS	80% COMPLETED	80% COMPLETED


## ELEVATION - FRONT & SIDE



## COMMON AREA WORK IN PROGRESS (1/4)



EXTERNAL PAINTING



FRONT SIDE DRIVEWAY

## COMMON AREA WORK IN PROGRESS (2/4)



OPEN PARTY AREA



MACHINE ROOM



SWIMMING POOL



LIFT

## COMMON AREA WORK IN PROGRESS (3/4)



FIRE FIGHTING



ELECTRICAL DUCT



FIRE ROOM

## COMMON AREA WORK IN PROGRESS (4/4)



ELECTRICAL ROOM




STP PUMP ROOM

## APARTMENT INSIDE (1/5)




MAIN DOOR



INSIDE DOOR

## APARTMENT INSIDE (2/5)



**PAINTING & FLOORING**

## APARTMENT INSIDE (3/5)



BALCONY FLOORING & HANDRAILS

## APARTMENT INSIDE (4/5)



COMMON WASH COUNTER



TOILET



RETICULATED GASLINE

## APARTMENT INSIDE (5/5)



UPVC DOOR & WINDOW

Thank you